











### COMPONENT CHECKLIST

|  |  |  |   |
|--|--|--|---|
| M5X15<br><br>X4<br>A1 | M6X15<br><br>X4<br>A2 | M8X15<br><br>X4<br>A3 | Ø16XØ6.2X1.5<br><br>X4<br>A4 |
|--|--|--|---|







**X1**

|  |  |   |
|--|--|---|
| Open-wrench<br><br>X1<br>B1 | 5mm<br><br>X1<br>B2 | 6mm<br><br>X1<br>B3 |
|--|--|---|







**X1**




|  |   |   |
|--|---|---|
| M8x12<br><br>X4<br>B4 | Ø16XØ8.2X1.5<br><br>X4<br>B5 | M8<br><br>X4<br>B6 |
|--|---|---|

**X2**

|  |  |  |   |   |  |
|--|--|--|---|---|--|
| M8x70<br><br>X3<br>C1 | Ø16XØ8.2X1.5<br><br>X12<br>C2 | M8x60<br><br>X1<br>C3 | Lag bolt<br><br>X4<br>C4 | Lag bolt<br><br>X6<br>C5 | Anchor<br><br>X6<br>C6 |
|--|--|--|---|---|--|

**X2**

|  |   |   |  |   |   |
|--|---|---|--|---|---|
| <br>X1<br>AA | <br>X2<br>BB | <br>X4<br>CC | M5<br><br>X2<br>DD | <br>X4<br>EE | <br>X2<br>FF |
|--|---|---|--|---|---|

|   |   |   |
|---|---|---|
| <br>X2<br>GG | <br>X2<br>HH | <br>X2<br>JJ |
|---|---|---|